


FIG.1







FIG.3






FIG.6





FIG.7








FIG.9








FIG.11





FIG.12






FIG.14




FIG. 15





FIG.16






FIG.17




FIG.18

## REPLACEMENT SHEET

## Solar yield due to mirror collar (Dec 21) in Malaga, Spain




FIG.19




FIG.20




FIG.21

